Vernon-Brannan House 112-114 J Street Sacramento Sacramento County California

HABS, CAL, 34-SAC, H3-

PHOTOGRAPHS

ARCHITECTURAL DATA FORM

Historic American Buildings Survey
Heritage Conservation and Recreation Service
Department of the Interior
Washington, D. C. 20243



United States Department of the Interior Heritage Conservation and Recreation Service Washington, D.C. 20243 NATIONAL ARCHITECTURAL AND ENGINEERING RECORD HISTORIC AMERICAN BUILDINGS SURVEY

ARCHITECTURAL DATA FORM

STATE	COUNTY		BS CAL 35	NITY	
CALIFORNIA	1	ACRAMENTO	SACRAMENTO		
HISTORIC NAME OF STRUCTU VERNON-BRANNAN HOUS		IRCE FOR NAME) 1 sources.)		HABS NO. CAL-179	
SECONDARY OR COMMON NAME	S OF STRUCTURE				
COMPLETE ADDRESS (DESCRI	BE LOCATION FOR	R RURAL SITES)			
DATE OF CONSTRUCTION (IN Built 1853.	CLUDE SOURCE)	ARCHITECT(S) (IN Builder, H. E. F		mento's first	
SIGNIFICANCE (ARCHITECTU Operated as a hotel	l by various own	CAL, INCLUDE ORIG ners until 1918.		RUCTURE)	
STYLE (IF APPROPRIATE)					
MATERIAL OF CONSTRUCTION Painted brick.	(INCLUDE STRUC	TURAL SYSTEMS)			
SHAPE AND DIMENSIONS OF S 43'(five-bay front)	•			IGES ARE ACCEPTA	PLE)
EXTERIOR FEATURES OF NOTE bays and a row of of slightly projecting or glazed window and iron paneled pilast INTERIOR FEATURES OF NOTE	oversized dentily pedimental head door transom ters with central	ls between the cor ads on consoles, f openings with cor al decoration; sid	nsoles; second- First floor has Ener brick pila Newalk canopy a	floor windows h round-arched b sters and four t second-floor	ave lind/ cast- level
panels, angle-iron		on remo, ir nor	one one one i	ecent metal dec	Oracijy
MAJOR ALTERATIONS AND ADD	DITIONS WITH DA	TFS			
In restoration 1978					
PRESENT CONDITION AND US	E	<u> </u>			
OTHER INFORMATION AS APPI	ROPRIATE				